NIOSH/MSHA Testing of the four Biomarine, Biopak 240S, Closed-Circuit Self-Contained Breathing Apparatus (SCBA) involved in the Storm Decline mine fatalities and rescue efforts

Prepared by Staff NIOSH/ National Personal Protective Technology Laboratory MSHA/ Pittsburgh Safety and Health Technology Center

April 3, 2003

NIOSH/MSHA Testing of the four Biomarine, Biopak 240S, Closed-Circuit SCBA involved in the Storm Decline mine fatalities and rescue efforts

Purpose:

The purpose of the investigation was to determine if the Biomarine, Biopak 240S, Closed-Circuit SCBAs involved in the Storm Decline mine fatalities and rescue efforts were in conforming condition with regard to NIOSH/MSHA approval, and to run tests using a metabolic breathing simulator to make operational evaluations as compared to baseline testing of a new apparatus.

The objectives of the testing were:

- 1. To document the condition of the apparatus as received;
- 2. To determine if the four apparatus conform to NIOSH/MSHA approval requirements;
- 3. To assist MSHA in pursuing related laboratory inquiries.

Prior to inspection or testing, a protocol governing the investigation was developed and accepted by both Agencies. The protocol took into account the following general considerations.

General Considerations:

- ❖ MSHA maintained the chain of custody while the units were in its possession.
- ❖ Parties to the testing of the apparatus were MSHA and NIOSH. Both Agencies permitted affected parties to observe this testing. However, control of the tests and the test conditions remained in the hands of MSHA and NIOSH.
- ❖ Observers attending the testing included two representatives from Barrick Goldstrike Mining, two from Biomarine, and one consultant representing the attorney for the victims' families. The consultant was the only observer who chose to observe throughout the entire testing process.
- ❖ The role of the observers was simply to observe. They were not permitted to interfere with the testing or test procedures.

- ❖ Testing began on November 25, 2002, at NIOSH's laboratory facility (NPPTL) at Bruceton, Pennsylvania, and continued until December 16, 2002. Additional tests on Apparatus #10 were conducted at the Biomarine manufacturing facility. NIOSH and MSHA personnel, the consultant, and the Biomarine representatives were present for these tests.
- Units were opened, inspected, and tested in the presence of investigators from MSHA and NIOSH and the observers.
- No human subject tests were conducted. A Breathing and Metabolic Simulator (BMS) was used to make functional assessments of the devices' performance. (This testing was not regarded as a direct substitute for human subject testing specified at Title 42, Code of Federal Regulations, Part 84.)
- ❖ The time frame for testing was governed by findings and the availability of supplies and consumables. It should be noted that both Agencies were in agreement on the acceptability of any components or supplies needed for nominal refurbishment when testing. The Agencies used oxygen provided by MSHA's mine rescue team and other material as obtained from the Barrick Goldstrike mine rescue station.

Test Protocol and Results:

- ❖ Step 1: Perform received-hardware inspection.
 - All package-opening actions were videotaped.
 - With minimal disturbance to the units, the physical condition of each unit with respect to approved condition was evaluated. Each apparatus was named according to the number on its outer housing, and each number was unique. (Apparatus names were: #1, #7, #10, and #15.)
 - All observations were recorded. Units and original packaging were retained as evidence and remained in MSHA's custody throughout.
 - Figure 1a, Appendix III, is a photograph of the units after unpacking.
 - Figure 1b, Appendix III, is an engineering drawing of a Biopack 240S, which is included for the sake of reference.
 - Spreadsheet 1, Appendix III, is a summary of the initial visual inspection findings.
- Step 2: Oxygen Cylinder Gas Analysis
 - The purpose of this test was to sample and analyze the chemical composition of the gases remaining in each oxygen cylinder.

- Figure 2, Appendix III, shows cylinder BA253, which has a nonstandard gauge, next to cylinder WJ173, which has a standard gauge.
- Spreadsheet 2, Appendix III, is a summary of oxygen cylinder gas analysis results.
- A copy of the MSHA gas analysis report is attached as Appendix I.
- It should be noted that all of the cylinders were nearly empty. Also, there was a spare cylinder, WJ188, which was packed in the box that contained Apparatus #7.
- ❖ Step 3: Run 30-minute BMS test on units in as-received condition.
 - The purpose of this test was to determine life support performance, running the units in an as-received condition. Because the oxygen cylinders on all four apparatus were nearly empty, they were replaced with fully charged cylinders and each unit was tested on the BMS for 30 minutes.
 - The BMS tests performed on the recovered Biopak 240S's were conducted according to the experimental procedure documented in NIOSH RI 9650, "Performance Comparison of Rescue Breathing Apparatus" (ISSN 1066-5552).
 - During the tests, life support variables such as breathing gas concentrations, pressure drops, and gas temperature were monitored and recorded on a continuous basis.
 - The units were used, left in the mine, and later recovered. Therefore, the test results were not expected to be indicative of a brand new unit. Furthermore, the results may not be indicative of how the units performed at the time of the accident.
 - Figure 3, Appendix III, is a photograph of a 30-minute BMS test on Apparatus #7.
 - Spreadsheet 3, Appendix III, contains a summary of the test results.
 - Charts 3a through 3d, Appendix III, are graphs showing how each apparatus performed compared to a new apparatus.
 - Each chart displays the average value over the test duration for the named variable.
 - All performance criteria compared well with the baseline test.
- Step 4: Restoration of Oxygen and Scrubber
 - Restoration meant refilling oxygen and scrubber, as well as freezing the Gel Tube freeze form.
 - Figure 4a, Appendix III, is a photograph of the restoration process.

- Spreadsheet 4a, Appendix III, summarizes the findings of the visual inspection that took place during the restoration.
- Figure 4b, Appendix III, is a photograph of Apparatus #10, showing a Gel Tube installed in the coolant canister.
- Figure 4c, Appendix III, is a photograph of Apparatus #1, showing that the coolant canister is empty and no Gel Tube is installed.
- In addition, samples of the scrubber material were collected and analyzed.
- Spreadsheet 4b, Appendix III, reports the results of the scrubber material analysis.
- The MSHA scrubber material analysis report is attached as Appendix II.
- ❖ Step 5: Run 2-hour BMS test on units with consumable supplies restored.
 - The purpose of this test was to determine if life support performance conformed to BMS baseline tests when the units were nominally refurbished.
 - Baseline testing was conducted with a new Biopak 240S.
 - Each unit, after it was refurbished, was run for 2 hours on the BMS.
 - Spreadsheet 5, Appendix III, contains a summary of the test results.
 - Charts 5a through 5d, Appendix III, are graphs showing how each apparatus performed compared to a new apparatus.
 - Each chart displays the average value over the test duration for the named variable.
 - With the exception of the higher inhalation and exhalation pressures noted on Apparatus #10, all performance criteria compared well with the baseline test.

Step 6: Bench Testing

- The purpose of this step was to run the required bench tests, as specified in Biomarine Biopak 240S Bench Manual, which must be performed prior to normal use. These tests included: High-pressure leak test, Low-pressure leak test, Flow test, and Face piece leak test.
- Since the chest gauge on Apparatus #15 was found to be leaking, it was replaced with a new one. Figure 6a, Appendix III, is a photograph showing the leak at the chest gauge. The leak rate for chest gauge was quantified at about 243 ml/minute.
- In addition to the leaky gauge, another leak was discovered in Apparatus #15 at a T-connection during the high-pressure leak test. Figure 6b, Appendix III, is an engineering drawing identifying the

- location of the leak at the T-connection. Figure 6c, Appendix III, is a photograph of the T-connection leak.
- Spreadsheet 6, Appendix III, summarizes the bench test findings.
- ❖ Step 7: Run certification bench tests which are required for approval of SCBAs under 42 CFR Part 84.
 - Spreadsheet 7a, Appendix III, contains the applicable certification bench tests.
 - Although the certification bench tests required that an apparatus be partially disassembled, the tests were nondestructive.
 - Figure 7, Appendix III, is a photograph of NIOSH 136, Demand Flow Test. It is included as an example.
 - Spreadsheet 7b, Appendix III, summarizes the findings of the tests.
 - It should be noted that, on Apparatus #15, the leak previously identified as being associated with the chest gauge was, in fact, located at the point where the gauge was connected to the flexible hose.
 - Evidence pointing to the gauge connection was the presence of water deposits on the chest gauge O-ring seal, as well as direct confirmation that the gauge worked properly.
- Step 8: Special BMS Tests
 - Because Apparatus #10 and #15 did not have Gel Tubes, 2-hour BMS tests were conducted to evaluate how well all four apparatus performed without coolant.
 - Apparatus #10 and #15, the two that arrived without Gel Tubes, were run in that condition, while the other two, Apparatus #1 and #7, were run with Gel Tubes, which were not frozen.
 - Spreadsheet 8, Appendix III, contains a summary of the test results.
 - Charts 8a through 8d, Appendix III, are graphs showing how each apparatus performed compared to a new apparatus with a frozen Gel Tube.
 - Each chart displays the average value over the test duration for the named variable.
 - With the exception of the higher inhalation and exhalation pressures noted on Apparatus #10, all performance criteria compared well with the baseline test.

Discussion:

❖ Testing began on November 25, 2002, at NIOSH's NPPTL at Bruceton, Pennsylvania, and continued until December 16, 2002.

- ❖ The objectives of the testing were accomplished.
 - The condition of the four Biopak 240S SCBAs, as received, was documented.
 - The life-support performance of each unit was evaluated according to a BMS test protocol and compared to benchmark test results for a new apparatus. All four apparatus were subjected to a battery of NIOSH/MSHA approval tests.
 - To assist MSHA in pursuing related laboratory inquiries, special 2hour BMS tests were conducted to evaluate how well the apparatus performed without coolant compared to a new apparatus with coolant.
- Spreadsheets 9a and 9b, Appendix III, are executive summaries of the test results, listing all of the differences or exceptions discovered during the course of testing.
- ❖ The findings of nonconformance are listed below:
 - As received from the mine, Units #10 and #15 did not have Gel Tubes installed. Use without a Gel Tube does not conform to conditions of approval.
 - One of the oxygen cylinders shipped with the apparatus had a nonconforming gauge.
 - o As received, Unit #15 had two high-pressure leaks. The leak at the chest gauge was detected during BMS testing, the other was discovered while oxygen and scrubber were being restored. The chest gauge leak was later measured at 243 ml/minute. The second leak was detected by following the approved bench procedure for preparing the apparatus. The second leak was located at the "T" connector, making it impractical to measure. Either leak would cause the apparatus not to conform to conditions of approval.
 - o During NIOSH certification tests, a number of failures were observed. Failure during any of the tests indicates that the apparatus is nonconforming.

- All four apparatus failed the relief valve pressure test.
- All four apparatus failed the exhalation resistance test
- Units #1, #7, and #10 failed the inhalation resistance test.
- Unit #15 failed the alarm pressure activation test.
- Unit #1 failed the alarm sound level test.
- ❖ These findings of nonconformance need to be viewed along with the results of BMS testing. The results compare the overall life support performance of Units #1, #7, #10, and #15 against a baseline of a new apparatus in the same configuration. All the apparatus, with the exception of Unit #10, had comparable performance to the baseline. Unit #10 exhibited higher exhalation breathing resistance, as well as higher average and minimum inhaled CO₂ concentrations.
- ❖ Because unit #10 exhibited higher exhalation breathing resistance values than the other units tested, NIOSH and MSHA took the unit to Biomarine's facility in Exton, Pennsylvania, on January 30, 2003, for the purpose of subjecting the unit to Biomarine's examination. It was found that the exhalation breathing resistance values were reduced to within Biomarine's specifications through the application of routine maintenance procedures.

Biomarine makes use of a PosiCheck breathing machine to measure breathing resistance. Performing maintenance in a step-by-step fashion, the breathing resistance was measured after each maintenance procedure was completed. The procedure that had the largest effect was the relubrication of the relief valve.

When the unit was returned to Pittsburgh, exhalation breathing resistance was measured again to confirm that the procedures had indeed lowered the breathing resistance. Testing was performed on February 12, 2003. Exhalation resistance values were reduced and were found to be in the approximate range of the values measured on units #1, #7, and #15. These results underscore the significance of strictly following all field maintenance procedures according to the methods the manufacturer stipulates.

Appendix I

MSHA Gas Analysis Report

Request for Laboratory Analysis

U.S. Department of Labor Mine Safety and Health Administration

† Required for Methane Liberated in 24 hrs



									
Event Number			2. Mine ID N	umber					
1. Event raniber			26-0230D						
3. Mine/Mill Name			4. Company	NO 72	- JP P	· · · · · · · · · · · · · · · · · · ·			
	ATION DI	FULLE	BAR	RICK GOL	D STRIK	É			
STORM EXPLORA 5. Contractor Name/Nu	mber		6. Commodi	y		,			
7. Collector JALASA	1/ROBIN	150 d	8. AR Numb	er					
9. Field Office	1/1/0010	/							
						· ·			
					· · · · · · · · · · · · · · · · · · ·				
Sampling Data	-7	002087397	2002087 PA8	2002087/399	200 2087400	200 2087401			
	Control/Blank		<i>></i>	\ \	\	✓			
10. Area/Personal (A/P)		AIR CYLI		`	\rightarrow	>			
11. Date Collected	·	11/25/02	11/25/02	11/25/02	11/25/02	11 25 02			
12. Time Collected				1. 1		, , .			
13. Pre-seal Intact (Y/N)									
14. Field Sample No.		MZ 188	WJ 173	BA 253	MILIS	WJ 135			
15. Sample Type*	СВ	# 15	#11	#5	#3	#1			
16. Analysis Requested		. بر		, , ·	p	G			
Note: Must match with 15.		6	G	G	b	0			
17. Flow Rate (LPM)									
18. Material Listed (Y/N)	,								
19. Job Code									
20. Job Description									
21. Last Name									
22. First Name									
23. Location Code									
24. Location/Site Description					,				
25. Miners Exposed (Y/N)									
26. Personal Protection (Y/N)									
27. Volume of Air (cfm) †									

*SAMPLE TYPE Lis	t (common examples)
B - Bulk (silica, asbestos)	OV - Organic Vapor (badge)
CB - Controi/Blank	R - Respirable Dust (quartz)
F - Fiber (asbestos)	T - Total Dust (listed nuisance)
Hg - Mercury Vapor	W - Welding Fume (16 element
M - Mist (acid, caustic, oil)	WS - Wipe (Pb, Hg, Ag)
MD - Metal Dust (single, or 16)	ST - Silica Gel Tube (methanol)
MF - Metal Fume (single, or 16)	CT - Charcoal Tube (solvents)
G - Gas (vacuum sampiers)	MISC - Other (specify)
Special Instructions- Comments (optional)	

Interim MSHA Form 4000-29, Jun 00 (Revised)

Mine Safety and Health Administration Department of Labor

Pittsburgh Safety and Health Technology Center Laboratory Cochrans Mill Road, Building 38, Pittsburgh, PA 15236 Phone: 412-386-6979 Fax: 412-386-6154

MIKE VALOSKI COLLECTOR:

AR#:
FIELD OFFICE NAME: Pittsburgh Tech Support
ADDRESS: Toxic Agents Division, Bld 38
P.O. Box 18233
Brucetton PA, 15236

Barrick Gold Strike CONTRACTOR:
MINE NAME:
Barrick Go
COMPANY:
COMMODITY:
GOLD ORE NATE RECEIVED:
DATE RECEIVED:
DATE REPORTED:
11/25/02 2602300

ANALYTICAL REPORT

AR0012060754 Report ID: Page 1 of 4

Date Printed: Friday, December 6, 2002

GOLD ORE MINING, N.E.C. 11/25/2002

REMARKS:

LAB ID#	FIELD Type of Sample No Sample	Type of Sample	Type of INSTR\METHOD Sample	ANALYTE	RESULT
2002087397	WJ188 #15	Ģ	GC-GASGC	ACETYLENE	mdd pu
2002087397	WJ188 #15	Ģ	GC-GAS~GC	ARGON	% pu
2002087397	WJ188#15	- 5	GC-GAS~GC	CARBON DIOXIDE	0.01 %
2002087397	WJ188 #15	-5	GC-GAS-GC	CARBON MONOXIDE	mdd pu
2002087397	WJ188 #15	Ģ.	GC-GASGC	ETHANE	udd pu
2002087397	WJ188#15	-j-	GC-GAS-GC	ETHYLENE	mdd bu
2002087397	WJ188 #15	ċ	GC-GAS~GC	HYDROGEN	mdd pu
2002087397	WJ188 #15	G-	GC-GAS~GC	METHANE	% pu

RESULT COMMENT

Data apply only to the listed analyte for the specified sample. This report is intended only for the entity to which it is addressed. Calculations based on parameters received.

Method Detection Limit MDL

Limit of Quantitation Threshold Limit

Short Term Exposure Limit Not detected above MDL LOQ TLV STEL ND

SUPERVISOR NAME Michael Valoski / SUPERVISOR TITLE: Laboratory Supervisor SIGNATURE:

ROBINSON-JOSEPH

ANALYZED BY: APPROVED BY: Page 1 of 4

_							,			1		-		1			· .	
RESULT	2.00 %	95.97 %	mdd pu	% pu	0.02 %	mdd þu	urdd pu	mdd pu	1 ppm	% pu	12.74 %	85.98 %	mdd pu	% pu	%100	mdd pu	mdd pu	udd þu
ANALYTE	NITROGEN	OXYGEN	ACETYLENE	ARGON	CARBON DIOXIDE	CARBON MONOXIDE	ETHANE	ETHYLENE	HYDROGEN	METHANE	NITROGEN	OXYGEN	ACETYLENE	ARGON	CARBON DIOXIDE	CARBON MONOXIDE	ETHANE	ETHYLENE
Type of INSTR \ METHOD	GC-GAS-GC	GC-GAS-GC	GC-GAS~GC	GC-GAS-GC	GC-GAS~GC	GC-GAS~GC	GC-GAS~GC	GC-GAS~GC	GC-GAS~GC	GC-GÁS~GC	GC-GAS-GC	GC-GAS~GC	GC-GAS~GC	GC-GAS~GC	GC-GAS~GC	GC-GAS-GC	GC-GAS~GC	GC-GAS~GC
Type of Sample	Ġ	-5	ģ	Ġ	ģ	-5	G	ڻ ن	ڻ ٺ	ර	9	ප්	ტ	ģ	Ġ	-5	Ģ	- <u>5</u>
FIELD Sample No	WJ188#15	WJ188 #15	WJ173 #11	WJ173 #11	WJ173#11	WJ173 #11	WJ173 #11	WJ173 #11	WJ173 #11	WJ173 #11	WJ173 #11	WJ173 #11	BA253 #5	BA253 #5	BA253#5	BA253 #5	BA253 #5	BA253#5
LAB ID#	2002087397	2002087397	2002087398	2002087398	2002087398	2002087398	2002087398	2002087398	2002087398	2002087398	2002087398	2002087398	2002087399	2002087399	2002087399	2002087399	2002087399	2002087399

RESULT COMMENT
Data apply only to the listed analyte for the specified sample. This report is intended only for the entity to which it is addressed. Calculations based on parameters received. ANALYZED BY: APPROVED BY:

ROBINSON-JOSEPH GERO-ANDREW

SUPERVISOR NAME: Michael Valoski SUPERVISOR THAD Laboratory Superv SIGNATURE:

MDL Method Detection Limit
LOQ Limit of Quantitation
TLV Threshold Limit
STEL Short Term Exposure Limit
ND Not detected above MDL

mdd pu	CARBON MONOXIDE	GC-GAS~GC	-5	WJ135#1	2002087401
0.04 %	CARBON DIOXIDE	GC-GAS-GC	- 5	WJ135#1	2002087401
nd %	ARGON	GC-GAS~GC	5	WJ135#1	2002087401
mdd þu	ACETYLENE	GC-GASGC	-j	WJ135#1	2002087401
76.40%	OXYGEN	GC-GASGC		WJ112#3	2002087400
22.76%	NITROGEN	GC-GAS-GC	-5	WJ112#3	2002087400
% pu	METHANE	GC-GAS~GC	Ġ.	WJ112#3	2002087400
mdd pu	HYDROGEN	GC-GAS~GC	-9	WJ112#3	2002087400
uıdd þu	ETHYLENE	GC-GASGC	-b	WJ112#3	2002087400
uidd þu	ETHANE	GC-GAS~GC	G	WJ112#3	2002087400
uıdd pu	CARBON MONOXIDE	GC-GAS~GC	G-	WJ112#3	2002087400
.0.03 %	CARBON DIOXIDE	GC-GAS~GC	ტ	WJ112#3	2002087400
% pu	ARGON	GC-GASGC	Ġ	WJ112#3	2002087400
mdd pu	ACETYLENE	GC-GAS~GC		WJ112#3	2002087400
92.58 %	OXYGEN	GC-GAS-GC	Ġ	BA253 #5	2002087399
5.54 %	NITROGEN	GC-GAS~GC	Ġ	BA253 #5	2002087399
% pu	METHANE	GC-GAS~GC	Ġ	BA253 #5	2002087399
mdd pu	HYDROGEN	GC-GAS-GC	-Ð	BA253 #5	2002087399
RESULT	ANALYTE	Type of INSTR \ METHOD Sample	Type of Sample	FIELD Type of Sample No Sample	LAB ID#

RESULT COMMENT
Data apply only to the listed analyte for the specified sample. This report is intended only for the entity to which it is addressed. Calculations based on parameters received. ANALYZED BY: APPROVED BY:

ROBINSON-JOSEPH VALOSKI-MICHAEL

SUPERVISOR NAME: Michael Valoski SUPERVISOR THTED aborator Super SIGNATURE:

Method Detection Limit Limit of Quantitation Threshold Limit Short Term Exposure Limit Not detected above MDL

MDL LOQ TLV STEL ND

30

RESULT	uıdd pu	mdd pu	uidd pu	% pu	26.29 %	73.03 %
ANALYTE	ETHANE	ETHYLENE	HYDROGEN	METHANE	NITROGEN	OXYGEN
FIELD Type of INSTR \ METHOD Sample No Sample	WJ135#1 G- GC-GAS~GC	GC-GAS~GC	GC-GAS-GC	GC-GAS~GC	GC-GAS~GC	GC-GAS~GC
Type of Sample	-5	ģ	5	. ტ	ģ	ප්
FIELD Sample No	WJ135#1	WJ135 #1	WJ135#1	WJ135#1	WJ135#1	WJ135#1

2002087401 2002087401 2002087401 2002087401 2002087401

LAB ID#

2002087401

RESULT COMMENT
Data apply only to the listed analyte for the specified sample. This report is intended only for the entity to which it is addressed. Calculations based on parameters received.

ROBINSON-JOSEPH VALOSKI-MICHAEL SUPERVISOR NAME: Michael Valoski SUPERVISOR THTTB; Jahorapon, Superv SIGNATURE: ANALYZED BY: APPROVED BY:

Method Detection Limit Limit of Quantitation Threshold Limit Short Term Exposure Limit Not detected above MDL MDL LOQ TLV STEL ND

Page 4 of 4

Appendix II

MSHA Scrubber Material Analysis Report

MSHA Technical Support Dust Division

January 9, 2003

MEMORADNUM FOR JEFFEREY H. KRAVITZ

Chief, Mine Emergency Operations

THROUGH: EDWARD J. MILLER,

Chief, Pittsburgh Safety and Health Technology Center

ROBERT A. HANEY Chief, Dust Division

FROM: MARK H. WESOLOWKI

Lab Director

SUBJECT: Analysis of Bulk Samples of CO₂ Absorbent taken on

November 26, 2002 at the Storm Decline Mine,

Mine ID No. 26 02300

Six bulk samples were taken on November 26, 2002, as part of the Storm Decline Mine fatality investigation. Four of the six samples, were taken from self-contained breathing apparatus used during the incident; two samples were unused material from the operator's stock room. Six 4 oz. precleaned borosilicate glass VOC vials, with Teflon lined caps, were filled with each bulk. A portion of each sample was analyzed at the Pittsburgh Safety and Health Technology Center lab for moisture and a suite of 19 elements; other increments of each bulk were submitted to Data Chem Laboratories Salt Lake City, Utah facility, for the analysis of sulfides, cyanides, antimony, selenium, and mercury. The Dust Division has retained three vials of each sample.

A summary of the findings is presented below. All analyses were reported on an "as received" basis; the samples were not dried prior to analysis.

- 1. The antimony content of each sample was below the Method Detection Limit (MDL) of 3 ug/g (3 parts per million on a weight/weight basis). The analytical method employed for this analysis was NIOSH Method 7300.
- 2. Mercury was analyzed by EPA Method 7471; all results were below the MDL of .02 ug/g.

- 3. Cyanide was determined by EPA Method 9012; all results were below the MDL of .5 ug/g.
- 4. Data Chem employed NIOSH Method 7903 for the determination of sulfides. This method measures sulfide indirectly, after oxidation to sulfate, which is analyzed via ion chromatography. Any sulfate present in a form that was soluble in the dilute sodium carbonate/bicarbonate solution used to extract the sample, would be a positive interference to the sulfide determination. The reported sulfide values ranged from 41 to 55 ug/g; the results for the unused Limepak samples were 47 and 53 ug/g respectively.
- 5. Selenium was analyzed by NIOSH Method 7300. The result for the Device 10 sample was 40 ug/g, which was above the MDL of 30 ug/g but below the Level of Quantification of 90 ug/g. All other selenium results were below the MDL.
- 6. The results of the PSHTC Laboratory analyses are given in tabular form below. Moisture was determined by drying the samples at 105 C° for 2 hours, while the elemental analysis was performed by MSHA Method P-3, where 1.0 gram of bulk material was digested with nitric and hydrochloric acids and analyzed by ICP spectroscopy.

Sample	Unused Limepak	Device 1	RWMSHA 10640	Device 7	Device 10	Device 15
H ₂ O %	15.1	18.9	15.4	16.4	17.5	17.3
Aluminum ug/g	<u>470</u>	<u>450</u>	<u>450</u>	<u>410</u>	<u>480</u>	<u>460</u>
Arsenic ug/g	ND	ND	ND	ND	ND	ND
Beryllium ug/g	ND	ND	ND	ND	ND	ND
Cadmium ug/g	ND	ND	ND	ND	ND	ND
Calcium ug/g	400,000	380000	400,000	360,000	380,000	390,000
Chromium ug/g	(6)	(5)	(5)	(5)	(6)	(6)
Cobalt ug/g	ND	ND	ND	ND	ND	ND
Copper ug/g	ND	ND	ND	ND	ND	ND
Iron ug/g	380	350	350	330	380	360
Lead ug/g	ND	ND	ND	ND	ND	ND
Magnesium ug/g	1600	1500	1400	1400	1500	1500
Manganese ug/g	98	98	97	90	100	100
Molybdenum ug/g	ND	ND	ND	ND	ND	ND
Nickel ug/g	(2)	(2)	(2)	(1)	(2)	(2)
Potassium ug/g	110	100	110	90	120	110
Sodium ug/g	1300	1200	1100	1200	1300	1200
Titanium ug/g	(7)	(5)	(6)	(6)	(6)	(6)
Vanadium ug/g	(8)	(7)	(7)	(7)	(8)	(8)
Zinc ug/g	17	17	17	14	17	18

Data Chem also determined many of the same elements as part of their antimony and selenium protocol. Their results for calcium averaged approximately 10% higher; their magnesium results were 15% higher. The numbers in parentheses correspond to analyze masses that are above the method reporting limits for welding fumes; for bulk samples these values should be considered semi-quantitative.

Appendix III,

Figures, Spreadsheets, Charts

Speakheet 1: Visual Inspection	#1	#7	#10	#15
1) Readingsondestgruge	0psi	0psi	0psi	0psi
2) Recordtypeoffaepiere	Scott	Scott	Scott	Scott
3) Reardandtional facepiece				
a) lens	OK	OK.	OK	1scratch
b) hosesandcorrections (fortightness)	Geencometornot	OK.	Fæpiæwænt	ΟK
	tightered retightered		corrected to	
	with 1/8 thturn		breathinghoses	
c) partsmissingerelanaged	Arti-foglers missing	OK.	Arti-foglers missing	ΟK
d) imerapinplae	OK	OK.	OK	ΟK
e) inhalationandeshalationvalves	OK	OK.	OK	ΟK
f) Facepiecepatrunter	D16A011	D46A011	D16A011	D46A011
4) Checkapproval label	TC13F466	TC13F466	TC13F466	TC13F466
5) Checkserial runter	0001	0007	00010	0022
6) Checkifthereareanywon, missinger loose parts/danage.	a) Small dert inscrubber	21argedentsin	a)Smalldenton	Oxygencylindernt
	carnister, b) Bottondip	scribber	scrubber carnister, b)	secured
	ansaubberhausing not	carrister	Glinderstrap	
	engaged		neversed	
7) Chakantinandoylinderpessuegauge	0psi	0psi	0psi	0psi
8) Readposition of cylinder valve and the number of turns it is opened.	Closed	Closed	Closed	Closed
9 Chekydeardhardefcrosygencylinder.	OK	ΟK	OK.	OK
10) Chekhydrostaticchte	Mar-99	Mar-00	Mar-99	Mar-99
11) Chekpesueratingoncylinder	#NA	#NA	#NA	#NA
12) Checkserial number	BA253 (See Note)	W J 173	W J 135	W 112
13) Marufacturing chtecylinder	Ag94	Sep88	Sep88	Sep88
14) Checkcylinder, valvesandgruge for danage.	OK.	ĆΚ	ĆΚ	ÓΚ
15) Checkovygencylinderseelingwesherfordanage	OK.	СК	CK	OK

Nte Clumshighightedinbluerefertouritstakenintothemine by the minerescue team, while the yellowhighighted columns refer tourits worn by the victims.

<u>Nite</u> Apparatus#I, Item15 Glinder gegeis different from the other 3 Manufactured by IRTE

Nte: Anetracygncylinder was paded in the box which contained Apparatus #7. Its condition as received was 0 psi on cylinder guage and valved osad Hydrostatic test date was Mar-99, Manufactured date Sap-88, and serial number WM88.



Figure 1a (From left-toright) Apparatus #10, #15, #1 and #7.




Figure 1: Biopak 240S Flow Diagram

Figure 1b: Engineering Drawing of Biopak 240S from Biomarine Benchman Manual

Speedled 2 Oggr Glindr Ga Addysis	Space	#1	#7	#10	#5
Glindisoid nurber	V18 8	B53	VMB	VM 5	J12
Giratresae	Opsi.	0pi	0pi	Opsi.	Qri
Ossen	9597 %	698	6 8	673°	6 C
Nitogn	2009	6 5 42	6 42	6 2 9%	6 B
alon Dride	000%	6 012	6 2	6 049	6 03%
aton vito ide	000%	6 00%	6 0	6 00%	6 00%

Ne Overylind VIB variated the lox hit notice Apacts #7





Figure Qirodi BXB vill encontactact gage recticy linedry VIIB vill standard gage

Sada Si Bakany

Apartis	KR\$nK					B	p	F begins
1	0	8	6	5	4	25	7	Ne Ne
7	2	3	1	4	3	B	B	Ne
0	3	1	6	4	3	B	B	Ne
5	2	9	6	4	3	B	B	latim cagete Na)
Bile	1	8	8	2	2	2	B	Ne

McCogdod Anthrone 28 Juin



Figue Stri 18 Million parts 17


Figure 4b: Apparatus #10 with
GelPak missing


_	
with	
s #1	
Apparatus	
rat	
pa	led
N .	k installed
4c: ,	ns
4	<u>.</u>
Figure 4	GelPak
ಕ	\equiv
rŦ.	7


dætto mællecær	Œ	Œ	(
			Y
September 1			
		The state of the s	FOOT STORY

Suzdat4 Retation Operate Buller #1 #7 #10 #5 1) Scoodvisalispection (alcoporate and 2lageditsin a\Small dettin aStallation Oxerolinatrat losingsosigsosver, dose, chagorlose sulteranite; b) sulteranite souldercaniste; () served Gest gave conetionogatstatrazinairtedilityotte Ritordipon **Glindrstap** lekardresie **Brooktofuntiorundruse** sadberlansirgrat neasel nearly desirat engaged natholindrgage reading 2 Iracethorairgandenthoraserblyasvollas(Œ Œ Œ Œ ings Œ Œ Œ Œ 3 Cheksaulberfamped 4 Vaifytlattlessubberkampedatksstlaril/8 tide carted solent coage accord / 32 orte Œ Œ Œ **OX** outside la manage de la contracte de la contra cantalook 5 Vairytecoolionoftedsolertantlekto Œ Œ Œ Œ setatitisuptotlefillerlineortlecerterpost 6 Charachatzeands #**X**A #**X**A #**X**A #**X**A Note Note Note Note 7) Natedordanse 8 Gerkaintenentapantherk Gingsel Œ Œ **OX** Œ 9 Gi Thefreedom Œ Œ Nifing **Nating** 1) Carkforfammistured solvent pad Pac Œ 187









Speadsheet & Bench Testing Summary	#1	#7	#10	#15
Hghpesuelæktest	ОХ	σĸ	ОХ	Failed Leakat T- correction and drest gasge. (See engineering drawing)
Lowpesueleaktest	СК	ОК	ΟK	OK
Howtest	ΟK	ΟK	СК	OK
Facepiecelæktest	СК	ОК	ΟK	CK

Note "T" correction tightered with a 1/2 turn Crest gargereplace with an ewore



Figure 6a Leakatchest gauge on Apparatus #15



Figure6c Leakat Transation on Apparatus #15




Figure to Frightening drawingshowing the location (at arrow) of the leak at the Transaction on Apparatus #15

		Stylian
KARB		
KRED		
KRO	HAR	Zig
KARED		≠1 0m
KARB		78 000
KARD	REFUE	78 00
KRED	Ange	
KARCIA	Addre	Extension
KAROBA	Rivigak	
		ZZZ
		liste
		XIII sid
		Yelinih
RATE	AGIR	*************************************


Speedhet 76 NOT Brith Tests Sumary	Regionert	#1	#7	#10	#15
137 Constant Flow (CF)	=1.51/nim	1640L/nim	1510L/nim	1570L/nim	17351/nim
138 Ratief Value Ressure	028-075inH₂0	024inH20	0 <u>2</u> 0in H <u>2</u> 0	025inH ₂ 0	025inH <u>1</u> 0
135Extetion Resistance (EF).	=20in1+10	26in1-10	22in1-j0	32in1-j0	26in1-j0
135Extedion Resistance (ER) (Retherkaller maintenance)	=20in1±10			245in1√20	
12/ByPassFlow(BFP)	=30L/nim	220 L/nim	<i>22</i> 71./him	210L/nim	230L/nim
117 Irradaion Resistance (IR).	=0in1±0	-15inH ₂ 0	-05inH ₂ 0	-02inH ₂ 0	0jnH ₂ 0
12/4/kam/Hessure	600-750psi	683psi	632/036	65psi	7.55psi †
145Aam&urdLexe	=80dBA	794dBA	816dBA	841dBA	808dBA
136DenardCasHow(DDF)	=30L/nim	223 L/nim	1751/him	170L/nim	229 L/nim
149AFendie CaugeLeak	=3671/nim	009L/nim	0022T/viju	007L/nim	010L/nim
128Accuracy Cauge	Difeerce				
@ 00a	±150psi	Opsi	-55p cs i	-30psi	-15 psi
@1003	±150psi	-10psi	45 psi	-20psi	-10psi
@files	±150psi	-15psi	-25psi	-5p s i	-10psi
@10 03	±150psi	-40 3si	+10psi	+10psi	+15psi
@10 13	±150psi	-30psi	+20psi	-2 5ps	-15 psi
	±150psi	-40 psi	+25psi	+45 psi	-30 ₍₂₃₎



Note Failing esubsacind ateclmentet.

†Figues to vvisite average of fixeruns-damfailed to activate of linguistrum performed.

Figure 7. Patograph of NICSH Test 176 Denand Cas Flow on Apparatus#10



FARTAGET	# #	#	#10	#5
Gigstingsty l	Aging	Ø	Algino	S B
	Faction	Zagati n	Fisher	Segrato
Vahanakseptsalen	air) Rido		alouid	cel
MARINE LANGE	aldigo		Gala p	
			mel	
	Thinks	Sat	State	Sadd
Districte	Novel Novel Novel	None	Allina	
T		The same	1100	
			New	Gyani n
Sankliganaligation	No.	None		landan
egalle				reilgendrah
				dayai
	Ø	Ø	Nade	Nate
Tapadabite	actuals or	Ø	Ø	Ø
			None	Allicots
2 Bangio	Rossi	None		gg ate
ZIIIIARISTEDI				rened Blyin
				Helatt
	Œ	Ø	Ø	ontads
THEOREMAN	UX.	UX	UX	




Chart 3a: Breathing Resistance




Chart 3b: Oxygen




Chart 3c: Scrubber Performance




Chart 3d: Inhalation Temperature




Chart 5a: Breathing Resistance




Chart 5b: Oxygen




Chart 5c: Scrubber Performance




Chart 5d: Inhalation Temperature




Chart 8a: Breathing Resistance




Chart 8b: Oxygen




Chart 8c: Scrubber Performance




Chart 8d: Inhalation Temperature

